Name of Inspector: Frank Donroe	Signature: 2 Down		
Date of Inspection: 3-9-18	Time inspection started: 1pm		
) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDEN	TIFIED PROBLEMS IMMEDIATELY TO THE W	/EP COORDINATOR.	
Key: Satisfactory - S, Not Applicable - NA, See Comment Section - C	AREAS SUBJECT TO INSPECTION		Additional Comments
	Southside of Bldg.	Northside of Bldg.	
rocess Wastewater Management			
re there any hoses or signs of washing of vehicles or equipment (e.g. oats) outside?	S	s	*
sterview one employee to assiss compliance with this policy?			Name: Bill xxxxx
there a posting inside the building notifying workers of proper process aste water management?	S	S	
	S	S	×
ther Issues:			.,
vaste water management?  Are there posting outside the building notifying workers of proper process wastewater management  Other Issues:	s s	s s	×