| Name of Inspector: Frank Donroe | Signature: 2 Locana | | | |
|---|------------------------------------|---------------------|---------------------|--|
| Date of Inspection: 7-6-18 | Time Inspection Started: 10am | | | |
| 1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDE | NTIFIED PROBLEMS IMMEDIATELY TO TH | HE WEP COORDINATOR. | | |
| Key: Satisfactory - S, Not Applicable - NA, See Comment Section - C | AREAS SUBJECT TO INSPECTION | | Additional Comments | |
| | Southside of Bldg. | Northside of Bldg. | No horses on site | |
| Process Wastewater Management | | | | |
| Are there any hoses or signs of washing of vehicles or equipment (e.g. floats) outside? | S | S | | |
| Interview one employee to assiss compliance with this policy? | | | Name: Phil xxxxxx | |
| Is there a posting inside the building notifying workers of proper process waste water management? | S | S | | |
| Are there posting outside the building notifying workers of proper process wastewater management | S | S | | |
| Other Issues: | | 1 | Al | |